




Light Bulb Replacement:

Feb. 1, 2010

Replacement of light bulbs on the Zodiac SL5A aircraft using parts compatible with existing fixtures while maintaining compatibility with the current system is approved. All work should be done in accordance with appropriate manuals and using approved techniques and procedures.

Insure all information is reflected on the aircrafts log books. Keeps this letter as part of you aircraft history and maintenance records.

Regards,

Garry Webster
Director of Manufacturing
Aircraft Manufacturing & Design
478-374-2759
garry@newamd.com

415 Airport Rd. Eastman GA, 31023
Tel: 478-374-2SKY (4782-374-2759) Fax: 478-374-2793